EAST WALL (Looking East)

<u>Note</u>

The quantilies shown are for estimating purposes only. The actual area to be repaired will be determined by the Engineer at the time of construction. Actual repair locations shall be shown on the "As Built" plans.

<u>LEGEND</u>

-Polymer Modified Portland Cement Mortar

sq. m. - Square Meter

BILL OF MATERIAL - BOX CULVERT NO. 10

	Item	Unit	Total
MX032196	Polymer Modified Portland Cement Mortar	sq. m.	0.3

Quantity increased by 20% to account for deterioration since field inspection.

SHEET S8 OF 19

REVISIONS										33
NAME	DATE	ILLIN	IOIS DI	EPARI	MENI	OF I	RANS	POR	TATION	9803
			BOX	CULV	'ERT	EXT	ENS.	101	IS	Š.
		CONCRETE REPAIR DETAILS								Z
		вох	CUL	/. NC	. 10,	ST	A. 7	+18	39.092	-
		SCALE	NONE			DRA	AWN BY	N	MLB	
		DATE	DECEME	SER 10,	2006	CHE	CKED E	BY N	MTH	
										_

PLOT DATE = 3/20/2008

LIN ENGINEERING, LTD., 210 WEST CHESTNUT, CHATHAM, IL 62629 (217)-483-4168